


Sep. 28 - Oct. 1, 2021 | Rome, Italy

Rehabilitation of the Sacramento Convent Former Presi ent's Office











1856-1858







1833














OFFICE'S AREA





HERITAGE INSTITUTE FOTO, 1940









EXISTENT CLOISTER
CEMENT SCREED FLOOR UNRECOVERABLE
SICK PALM TREES











EXISTENT CLOISTER
TILE PANELS IN VERY POOR STATE OF CONSERVATION
SALT IN EVERY WALL

















ENTRANCE COURT YARD





LOST COLUMN













INTERIOR SPACES
MESSED UP






GROUND FLOOR PLAN





FIRST FLOOR PLAN















EXECUTION 🗒











EXECUTION





SUSTAINABLE PLACES 2021





FINAL RESULT











TILE PANELS RESTORATION













CLOISTER, GOUND FLOOR AND GARDEN

















CLOISTER, FIRST FLOOR GALLERY





FORMAL ESSENCIALIZATION

































INTERIOR STAIRCASE









KITCHENETTE

















FLOOR REINFORCEMENT

SUSTAINABLE

SHELVING DIVISIONS















FLOOR REINFORCEMENT FOR AC



DOUBLE WINDOWS











FINAL RESULT





LOGO FOR THE OFFICE

Thanks for your attention

pedrovaz@presidencia.pt blvaz@fa.ulisboa.pt

